



7.1.5 Bosch will consider the following unacceptable under warranty consideration:

Rejection Code	Description
R01	Part not supplied, manufactured nor remanufactured by Bosch.
R02	Material not available for inspection.
R03	No defect found.
R04	Out of warranty as stated in the "Limited Warranty Policy", based on the date of installation and removal.
R05	Information needed for processing was incorrect and/or incomplete.
R06	Normal wear and tear.
R07	Improper packaging
R08	Improperly capped or protected. Note: All CIS fuel distributors must have the plunger included and fitted with a suitable size protective cap or taped to the distributor body to prevent the plunger from falling out. Also, all fuel injection valves must be properly capped.
R09	Unit incomplete (missing parts, such as solenoids, etc.)
R10	Physically damaged. (dented, cracked, incomplete, in pieces, etc.)
R11	Electrically damaged. (burnt)
R12	Failure due to corrosion.
R13	Failure due to contamination.
R14	Unauthorized repair.
R15	Lack of or improper maintenance.
R16	Improper installation or adjustment.
R17	Improper application.
R18	Consequential damage.
R19	Warranty factor.

7.1.6 Credit will be issued, at current prices, for all accepted warranty returns.

7.2 Warranty Information

Each distributor is expected to assist in implementing the Bosch Warranty Policy and Procedure accessible through the Bosch Service Website (www.boschservice.com) as occasionally amended by supplier.

Remanufactured Exchange Program - Core Credit Values

8.1 WD Net core charges for remanufactured exchange units are shown by part number in the current price file.

Full credit is shown in the current price file. Cores returned within 90 days from the effective core price change date, will be credited at the old or previous core prices. After 90 days, the new core prices will apply.

Reduced credit is calculated at 50% or ½ the full core value.

MUST BE SENT BACK TO FACTORY
Testing/Processing Time: 30 45 days
(888) 715-3616 - www.boschautoparts.com